

Authorize photomask submission





Due to the relatively high cost of photomask fabrication, submission must be authorized by the project or group manager for each project under which a mask fabrication request is being submitted.

Step-by-step guide










These steps must be completed by the project or group manager. Once a user's account has been configured to allow photomask submission, they can [submit their mask for fabrication](#) using LMACS.

1. Login to [LMACS](#).
2. Click **Manage Managed Projects** from the upper-left menu bar.
3. Select the desired project and click **Users**.
4. Click the small info icon  next to the desired user.
5. Switch the **Can Submit Masks** slider from **No** to **Yes**.
6. You may optionally add a limit to the number of masks in the **Mask Limit** field. Leaving this blank allows for unlimited mask submissions.
7. Click **Update**.

Demo User 

NanoFAB NanoFab Staff_Training

Address	Unknown	
End Date	2012-11-01	
Spending Cap	0.00	
Warning Limit	0.00	
Can Submit masks	<input checked="" type="checkbox"/> Yes	
Mask Limit	0	
Active	<input checked="" type="checkbox"/> Active	

[Remove](#) [Update](#)

Related content

- [Photomask Fabrication Pricing & Shipping Policies](#)
- [GDSII design suites](#)
- [Submit a file for photomask fabrication](#)
- [Submit a sample for analysis](#)
- [Register for nanoFAB access](#)