

# How-To Request an Alternative Approved PVD-75 Material



This procedure describes the process required to specify or request a specific material in Pocket 5 (other than the default, Ag) for the Electron-Beam Evaporation System #2 (PVD-75). See the Confluence Equipment page for the tool for the list of approved materials. In order to ensure that there is sufficient time to restore the default material, you **must** complete your session at least 30 minutes before the end of regular business hours (typically 5:00 pm).

<b>Equipment</b>	Electron-Beam Evaporation System #2 (PVD-75)
<b>Process Area</b>	DEPOSITION
<b>Location</b>	W1-060

## Step-By-Step Guide

1. [Create a new request in LMACS](#)
  - a. Enter **PVD-75 Material Change** for the Title.
  - b. Select the **Equipment Configuration Type**.
  - c. Select **Electron-Beam Evaporation System #2 (PVD-75)** for the Equipment.
  - d. In the **Summary**, enter the desired deposition material from the approved list (e.g., Cu).
2. Add a new **Booking** within the request, selecting the **Electron-Beam Evaporation System #2 (PVD-75)**.
  - a. Add an additional 30 mins to the beginning and end of your processing time to allow for the material changes.
  - b. A nanoFAB staff member will change the crucible material during these additional 30 minute slots.
3. Once the material has been changed, a comment will be added to the request.
4. Login and use the system as usual and you will be billed for the actual used time.